		NTSB ID: DCA05MA070		Aircraft Registration Number: N803MD	
		Occurrence Date: 06/07/2005		Most Critical Injury: Fatal	
		Occurrence Type: Accident		Investigated By: NTSB	
Location/Time					
Nearest City/Place Washington		State DC	Zip Code 20001	Local Time 0641	Time Zone EDT
Airport Proximity: On Airport		Distance From Landing Facility:		Direction From Airport:	
Aircraft Information Summary					
Aircraft Manufacturer Embraer		Model/Series 170		Type of Aircraft Airplane	
Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
<p>Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:</p> <p>On June 6, 2005, at 0641 EDT, an NMC-Wollard mobile belt baggage loader, model number TC-888 (serial number TC-888-841, USAirways identification number LD 667) was driven under and struck a USAirways Express Embraer EMB-170, registered in the United States as N803MD. This occurred while the flight crew was preparing the aircraft to operate as USAirways Express Flight 1821. The driver (Fleet Service Agent) of the belt loader was wedged into her seat by the bottom of the aircraft and the belt loader steering wheel and was fatally injured. No other injuries occurred. The aircraft and the belt loader received minor damage during the accident sequence. The event occurred at jetway 23 at Washington Reagan National Airport, Washington, DC.</p> <p>The fleet service agent was hired by USAirways on May 9, 2005, almost one month prior to the accident and had never driven a belt loader before joining that company. Her part-time duty hours were 0515 to 1145, with Wednesdays and Thursdays off. She received driver training on NMC-Wollard belt loaders on May 10, 2005, during a class titled Secured Area/AOA [airport operating area] Driver Training Class. Her Driver/Movement Training written examination test score was 100%. Her Driver/Non-movement Training written examination test score was also 100%.</p> <p>Interviews with several relatives revealed that the fleet service agent awoke at 0400 each workday and that her non-work activities in the 72 hours before the accident were routine. The night before the accident, she slept for about 6 hours. They stated that she was in good health, did not take any prescription medications, and was in normal spirits in the days before the accident. They also stated that she been involved in two traffic accidents within the last two years. She owned a Ford Taurus with an automatic transmission. According to the District of Columbia Department of Motor Vehicles, she received her first automobile driver's license on May 10, 2002.</p> <p>On the day of the accident the fleet service agent was wearing Rebok leather shoes with hard rubber foam soles. The tread patterns on the shoes were moderately worn, but only worn smooth in small areas on the outside edges of both heels.</p> <p>An autopsy revealed that the fleet service agent died of asphyxiation due to thoracic compression. Toxicological examination of blood and tissue samples revealed the presence of diphenhydramine at a concentration of less than 0.10 milligrams per liter. Diphenhydramine is an antihistamine contained in over-the-counter medicines such as Benadryl and is used to treat allergic reactions.</p> <p>Two security video cameras recorded portions of the accident sequence, but due to the camera angles, neither one showed enough of the sequence to enable the determination of vehicle speed at the time of impact with the airplane.</p> <p>The single eyewitness to the accident stated that he saw the fleet service agent approach the aircraft from the right rear, turn to the right around a fuel cart located off the right wing, and</p>					
FACTUAL REPORT - AVIATION					

National Transportation Safety Board

**FACTUAL REPORT****AVIATION**

NTSB ID: DCA05MA070

Occurrence Date: 06/07/2005

Occurrence Type: Accident

**Narrative** (Continued)

saw her trying to stop the belt loader. He speculated that her foot may have slipped off the brake pedal at that time.

The NMC-Wollard TC-888 belt loader is a four-wheeled gasoline powered, single seat vehicle equipped with an open driver's compartment and a 297.5 inch continuous moving belt assembly. The belt assembly can pivot, via hydraulics, at its rear end to facilitate different aircraft baggage door sill heights. When the belt assembly is lowered completely, the vehicle is 47.5 inches high, measured from the top of the steering wheel to the ground. The weight of the vehicle is 5,900 pounds.

An accelerator pedal and a brake pedal are located in the footwell of the belt loader. Both are metal, and the 2 by 4 inch brake pedal has raised holes in it to improve foot traction. The right edge of the pedal also has a 5/8 inch raised lip. The accelerator pedal is curved, and is 3 inches by 2 inches. The pedals are 4 inches apart laterally.

The initial examination of the vehicle revealed no external damage other than damage to the steering wheel, steering column, and the operator's seat. The upper portion of the steering wheel had struck the underside of the airplane during the impact sequence and was bent into an oval shape to the rear and in a downward direction. Deformation to the steering column originated at the point where it was held to the vehicle structure by a U-bolt. The backrest of the tubular steel seat was bent slightly to the rear. The front tires of the vehicle were deflated. This occurred after the accident during the rescue attempt. A small amount of hydraulic fluid was noted near the front right wheel assembly. There was no evidence of breaks or kinks in the hydraulic lines leading to the steering actuator.

The front tires were then reinflated and the vehicle was transported to a USAirways maintenance hangar. When the engine was started and the steering wheel was turned, the steering wheel would continue to rotate on its own after turning it about 30 degrees in either direction until the front axle stops were contacted. The wheel rotation could not be stopped by human intervention. The vehicle exhibited this tendency while lifted off the ground on a hydraulic lift, as well as while the vehicle was sitting on the pavement.

USAirways technicians then removed the accident steering column and steering control unit (SCU) and installed an operable steering column and SCU on the accident belt loader. When the accident steering column and steering control unit were removed from the vehicle, the steering column was observed to be deformed slightly in a downward direction.

The vehicle's brake system was then examined using a skid test. All four wheel assemblies achieved a locked condition when the brakes were fully applied. Also, the vehicle's maximum sustained speed of 18 miles per hour (mph) was measured utilizing a police speed-detecting laser.

An examination of the vehicle's engine and drive components revealed no damage or defects. The throttle return springs were firm and provided good return. The accelerator foot pedal was not damaged, and was able to move without any restrictions or objects impeding its movement.

The steering column and SCU were then examined using Hydraulic Control Division of the Eaton Corporation's final production test standards as examination guidelines. An Eton T-handle steering tool was fitted to the steering control unit in place of the bent steering column. When the control unit was pressurized and the T-handle was rotated, the steering system did not exhibit the runaway steering inputs that were previously noted. In addition, the steering column assembly mating connection to the SCU (a 12-tooth spline) exhibited rubbing along some of the spline teeth, indicating that abrasion against the SCU body had occurred. The accident SCU passed Eaton's final production test without any noted deficiencies.

The unit was then disassembled and examined at the Eaton manufacturing facility. During the

National Transportation Safety Board

**FACTUAL REPORT****AVIATION**

NTSB ID: DCA05MA070

Occurrence Date: 06/07/2005

Occurrence Type: Accident

**Narrative** (Continued)


examination, no broken or worn parts were noted, however several contact marks were found on the seal gland bushing and spool. These marks indicated that the spool had been side loaded. The resulting friction would not have allowed the spool to move freely with respect to the sleeve. Therefore, the control orifices inside the SCU would have been held open, and would allow the SCU to continue to command a steering wheel turn until the front axle stops were contacted. The evidence indicated that this defect noted in the steering mechanism was the result of the belt loader's impact with the airplane and not a preexisting fault.


An examination of the maintenance history of the vehicle was accomplished and no significant trends or recurring deficiencies were noted.


Weather conditions near the time of the accident included overcast skies, a forward visibility of 9 miles, a temperature of 68 degrees F, and a dew point of 64 degrees F. No precipitation was falling and the winds were out of 260 degrees at 4 knots.

The friction on the asphalt ramp surface was tested on the day following the accident using continuous friction measuring equipment. The condition of the ramp was the same as it was on the morning of the event. The average friction was measured at 0.740 at an average speed of 40.5 miles per hour.

-----

 <b>National Transportation Safety Board</b> <b>FACTUAL REPORT</b> <b>AVIATION</b>		NTSB ID: DCA05MA070				
		Occurrence Date: 06/07/2005				
		Occurrence Type: Accident				
<b>Landing Facility/Approach Information</b>						
Airport Name Washington Reagan National		Airport ID: DCA	Airport Elevation Ft. MSL	Runway Used NA	Runway Length	Runway Width
Runway Surface Type:						
Runway Surface Condition:						
Type Instrument Approach: NONE						
VFR Approach/Landing: None						
<b>Aircraft Information</b>						
Aircraft Manufacturer Embraer		Model/Series 170		Serial Number		
Airworthiness Certificate(s): Transport						
Landing Gear Type: Retractable - Tricycle						
Homebuilt Aircraft? No		Number of Seats: 70		Certified Max Gross Wt. 78153 LBS	Number of Engines: 2	
Engine Type: Turbo Prop		Engine Manufacturer: General Electric		Model/Series: CF34-8E	Rated Power: 14000 LBS	
<b>- Aircraft Inspection Information</b>						
Type of Last Inspection Continuous Airworthiness		Date of Last Inspection	Time Since Last Inspection Hours		Airframe Total Time Hours	
<b>- Emergency Locator Transmitter (ELT) Information</b>						
ELT Installed? No		ELT Operated? No		ELT Aided in Locating Accident Site? No		
<b>Owner/Operator Information</b>						
Registered Aircraft Owner  USAirways		Street Address P.O. Box 12346				
		City Pittsburg		State PA	Zip Code 15231	
Operator of Aircraft  Same as Reg'd Aircraft Owner		Street Address Same as Reg'd Aircraft Owner				
		City		State	Zip Code	
Operator Does Business As: US Airways Express				Operator Designator Code: USAA		
<b>- Type of U.S. Certificate(s) Held:</b>						
Air Carrier Operating Certificate(s): Flag Carrier/Domestic						
Operating Certificate:			Operator Certificate:			
Regulation Flight Conducted Under: Part 121: Air Carrier						
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only						
<div style="text-align: center;">FACTUAL REPORT - AVIATION</div> <div style="text-align: right;">Page 2</div>						

 <b>National Transportation Safety Board</b> <b>FACTUAL REPORT</b> <b>AVIATION</b>		NTSB ID: DCA05MA070								
		Occurrence Date: 06/07/2005								
		Occurrence Type: Accident								
<b>First Pilot Information</b>										
Name			City		State					
Sex:	Seat Occupied:	Principal Profession:		Certificate Number:						
Certificate(s):										
Airplane Rating(s):										
Rotorcraft/Glider/LTA:										
Instrument Rating(s):										
Instructor Rating(s):										
Type Rating/Endorsement for Accident/Incident Aircraft?										
Current Biennial Flight Review?										
Medical Cert.:		Medical Cert. Status:		Date of Last Medical Exam:						
<b>- Flight Time Matrix</b>	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument Actual	Instrument Simulated	Rotorcraft	Glider	Lighter Than Air
Total Time										
Pilot In Command(PIC)										
Instructor										
Last 90 Days										
Last 30 Days										
Last 24 Hours										
Seatbelt Used?		Shoulder Harness Used?			Toxicology Performed?		Second Pilot? Yes			
<b>Flight Plan/Itinerary</b>										
Type of Flight Plan Filed: IFR										
Departure Point		State				Airport Identifier		Departure Time		Time Zone
Same as Accident/Incident Location						DCA				EDT
Destination		State				Airport Identifier				
Type of Clearance: Unknown										
Type of Airspace:										
<b>Weather Information</b>										
Source of Briefing: National Weather Service										
Method of Briefing:										

 <b>National Transportation Safety Board</b> <b>FACTUAL REPORT</b> <b>AVIATION</b>			NTSB ID: DCA05MA070		
			Occurrence Date: 06/07/2005		
			Occurrence Type: Accident		


<b>Weather Information</b>					
WOF ID	Observation Time	Time Zone	WOF Elevation	WOF Distance From Accident Site	Direction From Accident Site
KDCA	0651	EDT	Ft. MSL	NM	Deg. Mag.
Sky/Lowest Cloud Condition: Few			7000 Ft. AGL		Condition of Light:
Lowest Ceiling: Overcast			25000 Ft. AGL		Visibility: 9 SM      Altimeter: 29.94 "Hg
Temperature: 20 °C		Dew Point: 18 °C		Wind Direction: 260	Density Altitude: Ft.
Wind Speed: 4		Gusts:		Weather Conditions at Accident Site: Visual Conditions	
Visibility (RVR): Ft.		Visibility (RVV) SM		Intensity of Precipitation:	
Restrictions to Visibility:					
Type of Precipitation:					

<b>Accident Information</b>					
Aircraft Damage: Minor		Aircraft Fire: None		Aircraft Explosion: None	
Classification:					

- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot					
Second Pilot					
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants					
Other Crew					
Passengers					
- TOTAL ABOARD -					
Other Ground	1				1
- GRAND TOTAL -	1				1

 <b>National Transportation Safety Board</b> <b>FACTUAL REPORT</b> <b>AVIATION</b>	NTSB ID: DCA05MA070	
	Occurrence Date: 06/07/2005	
	Occurrence Type: Accident	
<b>Administrative Information</b>		
Investigator-In-Charge (IIC) Robert P. Benzon		
Additional Persons Participating in This Accident/Incident Investigation:  Mark R Kimmel FAA, FSDO #27, Dulles, VA		
<div>FACTUAL REPORT - AVIATION</div> <div>Page 5</div>		